

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Dennis Oakley Environmental Engineer			
OGM	Jim Smith Environmental Scientist III			

Inspection Report

Permit Number:	C0150017		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, November 29, 2005		
Start Date/Time:	11/29/2005 9:06:00 AM		
End Date/Time:	11/29/2005 11:13:00 AM		
Last Inspection:	Wednesday, October 26, 2005		

Inspector: Jim Smith, Environmental Scientist III

Weather: cold, clear

InspectionID Report Number: 805

Accepted by: whedberg 12/9/2005

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	153.90
Total Disturbed	36.22
Phase I	
Phase II	
Phase III	

lineral Owners	ship T	ypes of	Operations

Mineral Ownership	Types of Operatio		
✓ Federal	✓ Underground		
State	Surface		
☐ County	Loadout		
✓ Fee	Processing		
Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Reclamation of the sedimentation pond was started the day before the inspection. Topsoil from the top 1.5 ft of the soil pile had been stockpiled, but no other work done at the time of the inspection.

Inspector's Signature

Thursday, December 08, 2005

Jim Smith, Environmental Scientist III Inspector ID Number: 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Tuesday, November 29, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	~		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓			
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	o Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	✓		✓	
22.	Other		✓		

Inspection Date: Tuesday, November 29, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permit was renewed August 29, 2005. The Permittee is in compliance with the permit conditions.

2. Signs and Markers

No noticeable new damage from firearms.

3. Topsoil

Topsoil from the top 1.5 ft of the soil pile had been stockpiled, but no other work done at the time of the inspection.

4.a Hydrologic Balance: Diversions

The only diversion is the ditch along the toe of the soil pile. It was clear of obstructions and maintained.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Reclamation of the sedimentation pond was started the day before the inspection. The pond was inspected on September 20, 2005, by John Christensen and Rick Cullum. Their report gave the remaining sediment storage capacity as 0.4 acre-ft.

4.d Hydrologic Balance: Water Monitoring

The sedimentation pond discharge is the only water-monitoring site. The latest DMR was for October, and there was no discharge reported.

8. Noncoal Waste

Mining and reclamation operations have not produced noncoal waste. There is some litter at both the reclaimed mine site and the sedimentation pond because of public use of these areas.

16.a Roads: Construction, Maintenance, Surfacing

The road has been graded to allow easier access during reclamation.

16.b Roads: Drainage Controls

The road grading left the road drainage controls intact.

21. Bonding and Insurance

There has been no change in bonding and insurance since the compete inspection in September 2005.